Name of work: Maintenance of bore well in Govindaraja Nagar Ward
in Bagalagunte ward no 14

Different color Before

&

ಸಹಾಯಕ ಅಭಿಯಂತರರು (ಯಂತ್ರಗಳು)

ಪೌ. ಪಾಲಿಕೆಯ ಅಧಿ ವಿಭಾಗ

Sreedevya Borewell

Name of work: Maintenance of bore wells in Sidedahalli ward
Amount sanctioned: Rs 10,000

Many thanks for Mounting of Borewell at Galadaballi Village
Grant No W/NO 14.

Name of work - Maintenance of Bore well at Siddalahalli village Ward in Bagalagalle A No 14.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073

Photos of work : Maintenance of Bore well in Siddahalli Village Ward
No Bagalagalli WARD 14

Name & Cost : Maintenance Work with Scaffolding
Amount in Rupees only

Name of work : Maintenance of Borewell in Sadadahalli Village
Level : Bagalakote Dist 14

Executive Engineer
R. Cauvery Sub Basin
Upper Bhadra Project Circle
Vanivilas Sagar, Bhadravathi - 577 373

Name of work:- Maintenance of Bore well in Siddalahalli village
at Begalapalli in 2014

Nearing of completion of borewell in Sixty feet wide gutter
Layout No 14